



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In Patent: 5,752,011 Ssued: May 12, 1998

Application No.: 08/262,754

Filed: June 20, 1994

Title: METHOD AND SYSTEM FOR CONTROLLING A PROCESSOR'S CLOCK

FREQUENCY IN ACCORDANCE WITH THE

PROCESSOR'S TEMPERATURE

Attorney Docket No.: CDT001

Certificate

Examiner: Heckler, T.

Group: 2316

JUN 1 6 2003

of Correction

CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the United States Postal Service in an envelope prepaid as First Class Mail to: Commissioner for Patents, Washington, DC 20231 on 3

C. DOUGLASS THOMAS
Printed Name

Signature

REQUEST FOR CERTIFICATE OF CORRECTION
OF APPLICANT'S MISTAKE (35 U.S.C §255, 37 C.F.R. §1.323)

Mail Stop 4
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450
Attn: Certificate of Correction

Sir:

Applicants herein request the Commissioner issue a Certificate of Correction under the conditions specified in 35 U.S.C. 255. The mistake(s) in the above-referenced patent to be corrected are of a clerical or typographical nature, or minor in character, and such mistake(s) occurred in good faith. The correction of these mistake(s) introduces no new matter nor requires reexamination.

Duplicate copies of Form PTO/SB/44 are enclosed for the Commissioner's review and use.

A check in the amount of \$100.00 is enclosed for the required fee as set forth in Sec. 1.20(a).

06/13/2003 DEMMANU2 00000006 5752011

01 FC:1811

100.00 OP

Respectfully submitted,

C. Douglass Thomas

Reg. No. 32,947

JUN 1 6 2005

Atty.Dkt.No.: CDT001

Page 1 of 1

Patent No. 5,752,011

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO :

5,752,011

DATED

May 12, 1998

INVENTOR(S):

C. Douglass Thomas

Alan E. Thomas
It is certified that error appears in the above-identified patent and that said Letters Patent

are hereby corrected as shown below:

Front Page Section [76], "Douglas" should be -Douglass--.

Col. 1, line 19, delete "p1" and begin new paragraph at "(a)";

line 20, after "control", insert --is--;

line 45, "It" should be --If--; and

line 61, "make" should be --made--.

Col. 2, line 2, "keyboard" should be --a keyboard-; and line 42, "maximizes" should be --maximize--;

Col. 3, line 16, "principals" should be --principles--.

Col. 6, line 12, begin new paragraph at "FIG. 5".

Col. 7, line 3, "low", should be "low,". line 7, delete "7"; and line 57, begin new paragraph at "Many".

Col. 8, line 64, "pulse" should be --pulses--.

Col. 9, line 30, "signal trigger" should be --signals trigger--.

line 41, "TABLE I" should be -- TABLE II--;

line 61, after "that", Insert --a--;

line 62, "addition" should be --additional--;

Col. 10, line 18, "follow" should be --following--; and line 27, "by" should be --be--.

Col. 11, line 66, delete "micro-".

MAILING ADDRESS OF SENDER: C. Douglass Thomas 1193 Capri Drive Campbell, CA 95008 PATENT NO. 5,752,011

No. of additional copies



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO :

5,752,011

DATED

May 12, 1998

INVENTOR(S):

C. Douglass Thomas

ΔI

Alan E. Thomas

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Front Page, Section [76], "Douglas" should be -- Douglass--.

Col. 1, line 19, delete "p1" and begin new paragraph at "(a)";

line 20, after "control", insert --is--;

line 45, "it" should be --if--; and

line 61, "make" should be --made--.

Col. 2, line 2, "keyboard" should be --a keyboard-; and line 42, "maximizes" should be --maximize--;

Col. 3, line 16, "principals" should be --principles--.

Col. 6, line 12, begin new paragraph at "FIG. 5".

Col. 7, line 3, "low", should be "low,".

line 7, delete "7"; and

line 57, begin new paragraph at "Many".

Col. 8, line 64, "pulse" should be --pulses--.

Col. 9, line 30, "signal trigger" should be --signals trigger--.

line 41, "TABLE I" should be --TABLE II--;

line 61, after "that", insert --a-;

line 62, "addition" should be --additional--;

Col. 10, line 18, "follow" should be --following-; and line 27, "by" should be --be--.

Col. 11, line 66, delete "micro-".

5,752,011

No. of additional copies

 \Rightarrow

1

MAILING ADDRESS OF SENDER: C. Douglass Thomas 1193 Capri Drive Campbell, CA 95008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO :

5,752,011

DATED

May 12, 1998

INVENTOR(S):

C. Douglass Thomas

Alan E. Thomas

It is certified that error appears in the above-identified patent and that said Letters Patent

are hereby corrected as shown below:

Eront Page, Section [76],

Col. 1, line 19, delete "p1" and begin new paragraph at

line 20, after "control", insert -- is--;

line 45, "It" should be --if--; and

line 61, "make" should be --made--.

Col. 2, line 2, "keyboard" should be --a keyboard--; and line 42, "maximizes" should be --maximize--;

Col. 3, line 16, "principals" should be --principles--.

Col. 6, line 12, begin new paragraph at "FIG. 5".

Col. 7, line 3, "low", should be "low,".

line 7, delete "7"; and

line 57, begin new paragraph at "Many".

Col. 8, line 64, "pulse" should be --pulses--.

Col. 9, line 30, "signal trigger" should be --signals trigger--.

line 41, "TABLE I" should be --TABLE II--;

line 61, after "that", insert --a--;

line 62, "addition" should be --additional --;

Col. 10, line 18, "follow" should be --following--; and line 27, "by" should be --be--.

Col. 11, line 66, delete "micro-".

MAILING ADDRESS OF SENDER: C. Douglass Thomas 1193 Capri Drive Campbell, CA 95008

5,752,011

No. of additional copies